Tom



Denison Mines (USA) Corp. 1050 17th Street, Suite 950 Denver, CO 80265 USA

Tel: 303 628-7798 Fax: 303 389-4125

www.denisonmines.com

December 27, 2010

Paul Baker State of Utah, Department of Natural Resources Department of Oil, Gas and Mining 1594 West North Temple, Suite 1210 P.O. Box 145801 Salt Lake City, Utah 84114-5801 DEC 2 9 2010

DIV. OF OIL, GAS & MINING

Paul Baker:

Re: Submission of Annual Reports for Utah Permits, Denison Mines (USA) Corp., Tony M (M/017/0049), La Sal/Snowball (M/370/026), Redd Block Four (M/037/0046), Rim-Columbus (M/370/006), Pandora (M/037/012).

Denison Mines (USA) Corp. is providing annual reports for the above referenced mines. Maps these mines have not changed from the maps currently on file with you.

Please contact me (303) 389-4136 if you have any questions.

Respectfully.

Christy Woodward, P.E.

Churp Woodward

Environmental Coordinator

Denison Mines Corp.

CC: Denison File

Terry Wetz, Denison Mines (USA) Corp. Philip Buck, Denison Mines (USA) Corp.

Enclosure.

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801

Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940

LARGE MINING OPERATIONS 2009 PROGRESS REPORT January 1, 2009 to December 31, 2009

The information required in this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, and the rules as under the Utah Minerals Regulatory Program.

	1.	Mine Permit Number: M/O 37 / O12
	2.	Mine Name: Pandora
	3.	Name of Operator/Permittee: Demson Mines (USA) Corp.
	4.	Note: If Operator's address, company representative or phone number have changed, please provide a replacement page for the Notice of Intention together with form MR-REV available on the Division's web page at https://fs.ogm.utah.gov/pub/mines/minerals_related/forms/MR-REV.pdf . Mine Location: Section 1, 7 29 3, R 24 E
	5.	Report the gross amount of ore mined and waste moved, and the disposition of the materials (onsite stockpiles, sold, waste pile, regraded, etc.):
		Gross Ore Mined Waste Material Moved New Disturbance Area Reclaimed Total Disturbed Area *Total mine disturbance from the beginning of mining operations through the end of 2009.
		Was the ore shipped off site? If not, where is the ore located? Ore was shipped to the white Mesa Mill, near Blanding, utah. Where is the waste located? Waste was placed underground and in approved surface locations.
	6.	Briefly describe the reclamation work performed during the past year. A map showing reclaimed areas and dates is suggested. (Submit form MR-SITE (https://fs.ogm.utah.gov/pub/mines/minerals_related/forms/MR-SITE.pdf) to apply for full or partial bond/site release). No reclamation was performed in 2010.
	7.	For large mines, include an updated map depicting surface disturbance and reclamation performed during the year (Rule R647-4-105). Current maps were provided in an NOI amendment in 2010.
correct		by certify, under penalties of law, the information provided in this report is true and best of my knowledge and belief.
		Name (Typed or Print): Philip Buck
		Title of Operator: Vice President & Mining
		Signature of Operators /// Stud
		Date: 12/17/10
pb OVEOBM	[C] was a stall	MB AB I MO2000 4